Map ID MAP FINDINGS

Direction Distance

Distance Elevation Site EDR ID Number

EDR ID Number

EDR ID Number

FN822 SOUTHWEST BROOKLYN SANITATION NY Spills S117974710
NW 1824 SHORE PARKWAY N/A

> 1 BROOKLYN, NY

1.132 mi.

5975 ft. Site 1 of 8 in cluster FN

Relative: SPILLS:

Higher Name: SOUTHWEST BROOKLYN SANITATION

Actual: Address: 1824 SHORE PARKWAY 8 ft. City, State, Zip: BROOKLYN, NY

Spill Number/Closed Date: 1503160 / 2015-06-24

 Facility ID:
 1503160

 Facility Type:
 ER

 DER Facility ID:
 162113

 Site ID:
 509451

 DEC Region:
 2

Spill Cause: Equipment Failure

Spill Class: C4 2401 SWIS: Spill Date: 2015-06-22 Investigator: **SXMAHAT** Not reported Referred To: Reported to Dept: 2015-06-22 CID: Not reported Water Affected: Not reported

Spill Source: Institutional, Educational, Gov., Other

Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0

Date Entered In Computer: 2015-06-22 Spill Record Last Update: 2015-10-28

Spiller Name: JOE SCARAMELLA
Spiller Company: J SCARAMELLA TRUCK
Spiller Address: 1824 SHORE PARKWAY

Spiller Company: 999

Contact Name: JOE SCARAMELLA

DEC Memo: "6/22/15: Mahat Spill was due to an overfill. Impacted stoned has

been removed from the site. Spill was very minor and no other resources were impacted. Further investigation is not warranted by

the Department. "

Remarks: "Spilled onto stone surface. Cleanup is completed."

All Materials:

Site ID: 509451 Operable Unit ID: 1258737 Operable Unit: 01 Material ID: 2261908 0010 Material Code: Material Name: hydraulic oil Case No .: Not reported Material FA: Petroleum Quantity: 2.00 Units: G

Recovered: Not reported Oxygenate: Not reported